

Message

From: Shea, Valois [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=A4217A71307D4429B7BDC7C80EB40C7D-SHEA, VALOIS]
Sent: 10/29/2015 9:34:50 PM
To: Julia Sage [jsage@poncatribes-ne.org]; alisha.bartling@santeeoep.com
CC: Holder, Stanley [Holder.Stanley@epa.gov]
Subject: web links for additional information
Attachments: DrillholeLocations.pdf

Thanks again for meeting with us yesterday!
Here are the web links I mentioned yesterday.

Here is the Wise-Uranium website for Dewey-Burdock:

<http://www.wise-uranium.org/upusasd.html>

This is a good place to start. This site has lots of links to NRC actions, Oglala Sioux Tribe concerns, links to Dakota Rural Action and Clean Water Alliance.

They have incorrectly posted a Nov. 19, 2009 second draft permit link for a Powertech permit related to the proposed uranium site in Colorado. It is for the Fox Hills Formation. I need to let them know about that.

This is the link to the UIC Dewey-Burdock permit applications:

<http://www2.epa.gov/region8/underground-injection-control>

They are about half-way down the page. There is a Class III permit app for the injection wells for uranium recovery and a Class V permit app for the deep injection wells for the disposal of the treated ISR waste fluids. I meant to mention that the treatment is to remove radium from the injectate before going into the disposal wells.

Here is the NRC Dewey-Burdock website:

<http://www.nrc.gov/info-finder/materials/uranium/licensed-facilities/dewey-burdock.html>

Here is the Nuclear Regulatory Commission NHPA 106 website for Dewey-Burdock:

<http://www.nrc.gov/info-finder/materials/uranium/licensed-facilities/dewey-burdock/section-106-project-docs.html>

Here is the NRC Dewey-Burdock license application and EIS website:

<http://www.nrc.gov/info-finder/materials/uranium/licensed-facilities/dewey-burdock/dewey-burdock-app-docs.html>

Here is the SD DENR website for all the Dewey-Burdock permitting actions:

<http://denr.sd.gov/powertech.aspx>

After our meeting I realized I should have mentioned that the Oglala Sioux Tribe is very concerned about all the exploration drillholes at the site. I have attached some information about that. The first map shows the location of over 5,000 exploration drillholes at the site. The OST is concerned these drillholes are not properly plugged and will cause leakage of the uranium-bearing lixiviant out of the injection intervals. The second map is the one you saw yesterday in the slide show showing the wellfield locations. In the third map I overlaid the drillhole map over the second map so you can see where the drillholes are in relation to the wellfields. I will give you a call to talk more about that next week.

Valois

Valois Shea
U.S. EPA Region 8
MailCode: 8P-W-UIC
1595 Wynkoop Street
Denver, CO 80202-1129

Phone: (303) 312-6276

Fax: (303) 312-6741

Email: shea.valois@epa.gov